

mult.

OUT59782

1966 SEP 12 23 36Z

P 122302Z SEP 66
FM NPIC WASHDC
TO RUCSC/SAC OFFUTT AFB OMAHA NEB
RUCVAA/4080 STRAT WG OL 19 BARKSDALE AFB LA
RUCVAA/2D RTS BARKSDALE AFB LA
RUEKDA/DIA WASHDC
RUECYH/NAVRECONTECHSUPPCEN SUTLAND MD
RUEPIA/CIA WASHDC
RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
RUWGAA/2 AF BARKSDALE AFB LA
BT

SECRET CITE NPIC 8445.
15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)
2D AF (FOR DI).

1. CAMERA B-15 WAS USED IN MISSION 8120 FLOWN ON 10
SEPTEMBER 1966. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH
SUPPCEN.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: PRESSURE ROLLER STATIC (CHATTER) OCCURS
INTERMITTENTLY ALONG THE OUTBOARD EDGE OF THE FILM THROUGHOUT
THE MISSION. THE INBOARD EDGE CONTAINS INTERMITTENT EDGE FOG
THROUGHOUT. A NARROW STREAK OF FOG STRIKES ACROSS FRAME 0003
AND EXTENDS FROM EDGE TO EDGE. MANUFACTURER'S SPLICES ARE
LOCATED IN FRAMES 0660 AND 2265. A HEAT SPLICE IS MADE THROUGH
FRAME 1161.

C. 9L SIDE: FOGGING FROM MINOR STATIC DISCHARGES
OCCURRED INTERMITTENTLY ALONG THE OUTBOARD EDGE OF THE FILM.
THE VERTICAL INDICATOR DOT APPEARED AS A RAGGED CIRCLE ON EACH
VERTICAL FRAME. NUMEROUS FINE PLUS DENSITY STREAKS, PARALLEL

13 SEP 1966

DISTRIBUTION		
Cy No.	Office	Action
1	File	
2	OS	
	ADMIN	
	SEC ER	
	P & DG	
	CCD	
	ICD	
	FD	
	ICD	
	ICD-ICB	
3,4	TID	
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy.
Sanitized

-2-

TO THE MAJOR AXIS, ARE PRESENT THROUGHOUT. THEY ARE READILY DETECTABLE IN LOW CONTRAST FRAMES. A SMALL AREA OF FOG IS PRESENT IN THE BORDER ALONG THE OUTBOARD EDGE OF FRAMES 1040, 1263, 1479 AND 1481. LIGHT STRIKING THE FILM AT THESE AREAS APPEARS TO BE THE CAUSE. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 1273. A HEAT SPLICE IS MADE IN FRAME 1211. THREAD LIKE OBSTRUCTIONS APPEAR TO BE ADHERING TO THE CENTER FIDUCIAL AND CAUSING IT TO APPEAR RAGGED. TITLING ON APPROXIMATELY TWO PERCENT OF THE FRAMES IS EITHER PARTIALLY REMOVED OR SMEARED. A NARROW STREAK OF FOG EXTENDING EDGE TO EDGE STRIKES ACROSS FRAME 0002.

D. BOTH SIDES: PRESSURE ROLLER STATIC (CHATTER) IS PRESENT INTERMITTENTLY ALONG THE INBOARD EDGE OF THE FILM THROUGHOUT. THE CLOCK COUNTER IN THE DATA CHAMBER IS NOT VISABLE ON ANY OF THE FRAMES. EDGE FOG IS PRESENT INTERMITTENTLY ALONG THE OUTBOARD EDGE OF THE FILM. THERE ARE 2281 TITLED FRAMES ON THIS MISSION.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING PROBLEMS.

3. POSITIVES:

A. PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS OBSCURE OR DEGRADE APPROXIMATELY 45 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-